

M/s Diamond Cements (Prop. HeidelbergCement India Limited)
Clinkerisation Unit, Narsingarh

Month: July 2019

TEST REPORT OF FUGITIVE EMISSION MONITORING

Sl. No.	Locations	Date	SPM ($\mu\text{g}/\text{m}^3$)
1	In between Lime Stone Stock Pile & Coal Yard	11.07.2019	996.12
2	Laterite Yard	11.07.2019	834.43
3	Near Crusher	12.07.2019	950.18
4	Near Raw Mill Silo	12.07.2019	813.01
5	Clinker Stock Pile	13.07.2019	878.62
6	Lime Stone Stock Area Line-3	13.07.2019	910.81
7	Coal Stock Area Line-3	15.07.2019	966.19

M/s Diamond Cements (Prop. HeidelbergCement India Limited)

Grinding Unit, Imlai

Month: July 2019

TEST REPORT OF FUGITIVE EMISSION MONITORING

Sl. No.	Locations	Date	SPM ($\mu\text{g}/\text{m}^3$)
1	Clinker Stock Pile	16.07.2019	932.18
2	Coal Yard	16.07.2019	846.41
3	Gypsum Yard	17.07.2019	925.52
4	Fly ash Handling System	17.07.2019	921.45
5	Near Cement Silo	18.07.2019	979.34

M/s Diamond Cements (Prop. HeidelbergCement India Limited)

Lime Stone Monitoring Mine, Patharia

Month: July 2019

TEST REPORT OF FUGITIVE EMISSION MONITORING

Sl. No.	Locations	Date	SPM ($\mu\text{g}/\text{m}^3$)
1	Near Loading Point - Belt Conveyor	22.07.2019	873.36
2	Haulage Road	22.07.2019	773.67
3	Near Crusher	23.07.2019	915.52
4	Near Lime Stone Stock Area	23.07.2019	762.89
5	Near Drilling Area	24.07.2019	825.81